

**Task Name: 032 Thou Parts**

Date: **4/15/2004** Totals: Area Util: **76.64 %**

Description: **Layout for Parts on .032" Sheets**

Weight Util: **... %**

Net Cost: **0.00**

Common Turn Rules = **True** : TurnOn: **Yes**

Gaps (Item-Item / Item-Edge): **0 / 0**

Area Mult: **100**

**Sheets / 2D Containers to Load:** SUMMARY - Available: Number 3 Area 489600 LoadWgt 0  
 Used: 2 460800 0

Container Type	Cost	Avail	Used	Mark	Length	Width	Area	LoadWgt
Sheet 032 (1'x2')	0	1	0	S32	1200	2400	28800	0
Sheet 032 (4'x4')	0	2	2	S33	4800	4800	230400	0

**Parts / 2D Boxes to Pack:** SUMMARY - Total: Number 49 Area 353141 Weight 0  
 Left: 0 0 0

Box Kind	Cost	Total	Used	Mark	Length	Width	Area	Weight	TurnOn
F03-07	0	1	1	B1	113	163	184	0	True
F10-14	0	2	2	B2	300	275	825	0	True
F10-15	0	1	1	B3	250	275	688	0	True
F23-02	0	1	1	B4	625	1232	7700	0	True
T07-06	0	1	1	B5	300	1450	4350	0	True
T07-07	0	1	1	B6	250	200	500	0	True
W14-03	0	16	16	B7	100	757	757	0	True
W23-08	0	4	4	B8	300	250	750	0	True
D02-09	0	4	4	B9	300	350	1050	0	True
D02-15	0	1	1	BA	2650	150	3975	0	True
D02-18	0	1	1	BB	150	150	225	0	True
D02-19	0	1	1	BC	150	150	225	0	True
F08-12	0	1	1	BD	200	300	600	0	True
F10-07L	0	1	1	BE	257	263	676	0	True
F10-07R	0	1	1	BF	257	263	676	0	True
F10-08	0	2	2	BG	169	375	634	0	True
F10-11	0	2	2	BH	275	175	481	0	True
P14-02	0	1	1	BI	1663	1125	18709	0	True
P14-03	0	1	1	BJ	650	400	2600	0	True
W10-07	0	2	2	BK	813	757	6154	0	True
W23-06L	0	1	1	BL	297	216	642	0	True
W23-06R	0	1	1	BM	297	216	642	0	True

Box Kind	Cost	Total	Used	Mark	Length	Width	Area	Weight	TurnOn
F07-01	0	1	1	BN	4800	4800	230400	0	True
F07-03	0	1	1	BO	3900	1150	44850	0	True