


3/16" dia clearance hole 2 places  
 (hole in spar cap assembly located by  
 transfer drilling through the spar web.)



When I made my spar assembly I laid everything out in millimeters which is why the decimals are not standard fraction conversions. These were made after the spar webs were all cut and drilled so they were made to match what was already done. *You may need to adjust the hole pattern for your spars* but the length of the short spacer should not need to be changed. (Note- I am a precision sheetmetal worker by occupation.)

Cap Spacers  
 .120 CRS  
 (10 sets)





